Oil Field Environmental Incident Summary

Responsible Party: T & R Transport

Well Operator: HRC OPERATING, LLC Well Name: MOLINE 157-100-20D-17-3H

Field Name: MARMON Well File #: 26211

Date Incident: 1/10/2014 Time Incident: 2145 Facility ID Number:

County: WILLIAMS Twp: 157 Rng: 100 Sec: 20 Qtr: SW SE

Location Description:

Submitted By: Dewey Cooper Received By:

Contact Person: Tristan Walker

1801 CALIFORNIA STREET

SUITE 3500

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.2 MilesDistance Nearest Water Well:0.2 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup Units

	Opinea	Omes	Accordica	Offico	
Oil	0	barrels	0	barrels	
Brine	2	barrels	2	barrels	
Other	0	barrels	0	barrels	

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None all contained to pad

Areal Extent:

Potential Environmental Impacts:

None all contained to pad

Action Taken or Planned:

Under investigation

Wastes Disposal Location: Halcon SWD

Agencies Involved:

Updates

Date: 1/13/2014 **Status:** Reviewed - Assigned to Other Agency **Author:** Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow (truck?), remained on location, according to the report. NDIC retains oversight.